
generator_name	NEWTON HEAT TRANSFER
lc_name:	Newton Heat Treating Company, Inc.
lc_calc_volume:	3.2109 tons

manifest_number	manifest_quantity_ton
88614635	2.2935 tons
88681783	0.9174 tons

07-28-89 SHIPPER 15446

State of California—Health and Welfare Agency
Form Approved OMB No. 2050-0039 (Expires 9-30-91)See Instructions on Back of Page 6
and Front of Page 7Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch typewriter).)

**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.

Manifest
Document No.2. Page 1
of 1Information in the shaded areas
is not required by Federal law.

3. Generator's Name and Mailing Address

NEWTON HEAT TRANSFER
19235 WALNUT DR., CITY OF INDUSTRY, CA

4. Generator's Phone (714 529-5956

A. State Manifest Document Number

88614635

B. State Generator's ID

5. Transporter 1 Company Name

OMEGA RECOVERY SERVICES

6. US EPA ID Number

ICIAID0412245001

C. State Transporter's ID

010381

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address

OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number

ICIAID0412245001

G. State Facility's ID

CAN04245001

H. Facility's Phone

(213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

a. WASTE PERCHLOROETHYLENE ORM-A UN 333# 1897

12. Containers
No. Type010
0112 DIM13. Total
Quantity

00550 G

14. Unit
Wt/Vol

Waste No.

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a.

b.

c.

d.

15. Special Handling Instructions and Additional Information

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

JAMES WHELAN

Signature

James L. Whelan

Month Day Year

10/10/89

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

ROBERT T. CIRINGIONI

Signature

Robert T. Ciringioni

Month Day Year

10/10/89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner, or Operator, Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

FRANK FORD

Signature

Frank Ford

Month Day Year

10/24/89

Do Not Write Below This Line

White: TSD/ SENDS THIS COPY TO DQHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

6022 A (1/85)

PA 5700-22

(Rev. 9-88) Previous editions are obsolete.

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8602; WITHIN CALIFORNIA CALL 1-800-852-7650

GENERATOR

TRANSPORTER

FACILITY

Please print or type. (Form designed for use on elite (12-pitch typewriter).

88681783
IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD 982 502 932		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address NEWTON HEAT TREATING INC. 19235 EAST WALNUT DR., CITY OF INDUSTRY, CA 91744						A. State Manifest Document Number 38681783				
4. Generator's Phone (714) 529-5956						B. State Generator's ID				
5. Transporter 1 Company Name OMEGA RECOVERY SERVICES						6. US EPA ID Number CAD 042 245 001		C. State Transporter's ID 110237		
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone 213 698-0991		
9. Designated Facility Name and Site Address OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602						10. US EPA ID Number CAD 042 245 001		E. State Transporter's ID		
								F. Transporter's Phone		
								G. State Facility's ID CAD 042 245 001		
								H. Facility's Phone 213 698-0991		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers No. Type		13. Total Quantity		
a. HAZARDOUS WASTE LIQUID, N.O.S ORM-A NA 9189 (PERCHLOROETHYLENE 60%, WATER 40%)						004 dm		002206		
b.								State 211,133		
c.								EPA/Other 100%, D030		
d.								State		
								EPA/Other		
								State		
								EPA/Other		
J. Additional Descriptions for Materials Listed Above PROFIEL NUMBER B 10828						K. Handling Codes for Wastes Listed Above a. 01 b. c. d.				
15. Special Handling Instructions and Additional Information										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.										
Printed/Typed Name PAUL BRODERICK					Signature <i>Paul Broderick</i>		Month Day Year 12/20/91			
17. Transporter 1 Acknowledgement of Receipt of Materials					Printed/Typed Name Robert T. CIRINGOM		Signature <i>Robert T. Ciringom</i>		Month Day Year 12/20/91	
18. Transporter 2 Acknowledgement of Receipt of Materials					Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space										
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										
Printed/Typed Name John HALL					Signature <i>John Hall</i>		Month Day Year 12/20/91			

generator_name	NEWTON HEAT TRANSFER
lc_name:	Newton Heat Treating Company, Inc.
lc_calc_volume:	3.2109 tons

manifest_number	manifest_quantity_ton
88614635	2.2935 tons
88681783	0.9174 tons

07-28-89 SHIPPER 15446

State of California—Health and Welfare Agency
Form Approved OMB No. 2050-0039 (Expires 9-30-91)See Instructions on Back of Page 6
and Front of Page 7Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch typewriter).

**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.

Manifest
Document No.2. Page 1
of 1Information in the shaded areas
is not required by Federal law.

3. Generator's Name and Mailing Address

NEWTON HEAT TRANSFER
19235 WALNUT DR., CITY OF INDUSTRY, CA

4. Generator's Phone (714 529-5956

5. Transporter 1 Company Name

OMEGA RECOVERY SERVICES

7. Transporter 2 Company Name

9. Designated Facility Name and Site Address

OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number

ICIAID042245001

A. State Manifest Document Number

88614635

B. State Generator's ID

C. State Transporter's ID

010881

D. Transporter's Phone (213) 698-0991

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

CANAD045001

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

WASTE PERCHLOROETHYLENE ORM-A UN 1897

12. Containers
No. Type010
0112 DIM CROSSED13. Total
Quantity14. Unit
Wt/Vol

G

15. Waste No.

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a. 01

b.

c.

d.

15. Special Handling Instructions and Additional Information

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR: If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

JAMES WHELAN

Signature

James L. Whelan

Month Day Year

10/30/89

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

ROBERT T. CIRINGIONI

Signature

Robert T. Ciringioni

Month Day Year

10/30/89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner, or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

FRANK FORD

Signature

Frank Ford

Month Day Year

10/30/89

6022-A (1/88)

5700-22

(9-88) Previous editions are obsolete.

Do Not Write Below This Line

While: TSDF SENDS THIS COPY TO DQHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA CALL 1-800-862-7650

GENERATOR

TRANSPORTER

FACILITY

Please print or type. (Form designed for use on elite (12-pitch typewriter).)

88681783
IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

CAD 982 502 932

Manifest
Document No.

2. Page 1
of

Information in the shaded areas
is not required by Federal law.

3. Generator's Name and Mailing Address

NEWTON HEAT TREATING INC.

19235 EAST WALNUT DR., CITY OF INDUSTRY, CA 91744

A. State Manifest Document Number

38681783

B. State Generator's ID

4. Generator's Phone

714 529-5956

5. Transporter 1 Company Name

OMEGA RECOVERY SERVICES

6. US EPA ID Number

CAD 042 245 001

C. State Transporter's ID

710237

D. Transporter's Phone

213 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address

OMEGA RECOVERY SERVICES

12504 E. WHITTIER BLVD

WHITTIER, CA 90602

10. US EPA ID Number

CAD 042 245 001

G. State Facility's ID

CAD 042 245 001

H. Facility's Phone

213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

a. HAZARDOUS WASTE LIQUID, N.O.S ORM-A NA 9189
(PERCHLOROETHYLENE 60%, WATER 40%)

12. Containers
No. Type

004 dm

13. Total
Quantity

002206

14. Unit
Wt/Vol

1. Waste No.

State 211,133

EPA/Other 004,0030

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

PROFIEL NUMBER B 10828

K. Handling Codes for Wastes Listed Above

a. 01

b.

c.

d.

15. Special Handling Instructions and Additional Information

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

PAUL BRODERICK

Signature

Paul Broderick

Month Day Year

02/20/91

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Robert T. CIBINCEON

Signature

Robert T. CIBINCEON

Month Day Year

02/20/91

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

John HALL

Signature

John Hall

Month Day Year

02/20/91

generator_name	NEWTON HEAT TRANSFER
lc_name:	Newton Heat Treating Company, Inc.
lc_calc_volume:	3.2109 tons

manifest_number	manifest_quantity_ton
88614635	2.2935 tons
88681783	0.9174 tons

07-28-89 SHIPPER 15446

State of California—Health and Welfare Agency
Form Approved OMB No. 2050-0030 (Expires 9-30-91)

Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6
and Front of Page 7Department of Health Services
Toxic Substances Control Division
Sacramento, California**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.

Manifest
Document No.

2. Page 1

of 1

Information in the shaded areas
is not required by Federal law.

3. Generator's Name and Mailing Address

NEWTON HEAT TRANSFER
19235 WALNUT DR., CITY OF INDUSTRY, CA

A. State Manifest Document Number

88614635

B. State Generator's ID

4. Generator's Phone (714) 529-5956

C. State Transporter's ID

01038X

5. Transporter 1 Company Name

OMEGA RECOVERY SERVICES

ICIAID042245001

D. Transporter's Phone

(213) 698-0991

7. Transporter 2 Company Name

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address

OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number

ICIAID042245001

G. State Facility's ID

CA0042245001

H. Facility's Phone

(213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

a. WASTE PERCHLOROETHYLENE ORM-A UN ~~333~~ 189712. Containers
No. Type

010

0112 DIM

13. Total
Quantity

cross

50 G

14. Unit
Wt/Vol

G

Waste No.

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a.

b.

c.

d.

15. Special Handling Instructions and Additional Information

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

JAMES WHELAN

Signature

James L. Whelan

Month Day Year

10/10/89

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

ROBERT J. CIRINGIONI

Signature

Robert J. Ciringioni

Month Day Year

10/10/89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

FRANK FORD

Signature

Frank Ford

Month Day Year

10/20/89

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

EPA 6022-A (1/88)

EPA 8700-22

EPA (9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

Please print or type. (Form designed for use on elite (12-pitch typewriter).)

88681783
IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8602; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD 982 502 932		Manifest Document No. 1111		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address NEWTON HEAT TREATING INC. 19235 EAST WALNUT DR., CITY OF INDUSTRY, CA 91744						A. State Manifest Document Number 38681783			
4. Generator's Phone (714) 529-5956						B. State Generator's ID 11111111			
5. Transporter 1 Company Name OMEGA RECOVERY SERVICES				6. US EPA ID Number CAD 042 245 001		C. State Transporter's ID 110237		D. Transporter's Phone 213 698-0991	
7. Transporter 2 Company Name				8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602				10. US EPA ID Number CAD 042 245 001		G. State Facility's ID CAD 042 245 001		H. Facility's Phone 213 698-0991	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers No. Type		13. Total Quantity	
a. HAZARDOUS WASTE LIQUID, N.O.S ORM-A NA 9189 (PERCHLOROETHYLENE 60%, WATER 40%)						dm		211,133	
b.								EPA/Other 1002, D030	
c.								EPA/Other	
d.								EPA/Other	
J. Additional Descriptions for Materials Listed Above PROFIEL NUMBER B 10828						K. Handling Codes for Wastes Listed Above a. 01 b. c. d.			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name PAUL BRODERICK				Signature <i>Paul Broderick</i>		Month Day Year 02/20/91			
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Robert J. CIRINCIONE		Signature <i>Robert J. Cirincione</i>		Month Day Year 02/20/91	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name John HAUTE				Signature <i>John Haute</i>		Month Day Year 12/24/91			

07-28-89 SHIPPER 15446

State of California—Health and Welfare Agency/
Form Approved OMB No. 2060-0039 (Expires 9-30-91)See Instructions on Back of Page 6
and Front of Page 7Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch typewriter).

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address NEWTON HEAT TRANSFER 19235 WALNUT DR., CITY OF INDUSTRY, CA		C I A I D 19 18 12 15 10 12 19 13 12		A. State Manifest Document Number 88614635	
4. Generator's Phone (714 529-5956		6. US EPA ID Number		B. State Generator's ID	
5. Transporter 1 Company Name OMEGA RECOVERY SERVICES		C I A I D 10 14 2 2 14 5 0 0 1		C. State Transporter's ID 010389	
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (213) 698-0991	
9. Designated Facility Name and Site Address OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602		10. US EPA ID Number C I A I D 10 14 2 2 14 5 0 0 1		E. State Transporter's ID 010389	
				F. Transporter's Phone (213) 698-0991	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. WASTE PERCHLOROETHYLENE ORM-A UN 1897		010	20550	G	State EPA/Other
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
		a. 01 b. c. d.			
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name JAMES WHELAN		Signature James L. Whelan		Month Day Year 10/10/89	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature Robert J. Cirincione		Month Day Year 10/10/89	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19:					
Printed/Typed Name FRANK FORD		Signature Frank Ford		Month Day Year 10/10/89	

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DSHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

06/04/2001 "ORIGINAL MANIFEST COPY"

generator_name	NEWTON HEAT TRANSFER
lc_name:	Newton Heat Treating Company, Inc. <i>2320</i>
lc_calc_volume:	3.2109 tons

manifest_number	manifest_quantity_ton
88614635	2.2935 tons
88681783	0.9174 tons

07-28-89 SHIPPER 15446

State of California Health and Welfare Agency
Form Approved OMB No. 2050-0039 (Expires 9-30-91)See Instructions on Back of Page 6
and Front of Page 7Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch typewriter).

**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.

Manifest
Document No.

2. Page 1

of 1

Information in the shaded areas
is not required by Federal law.

3. Generator's Name and Mailing Address

NEWTON HEAT TRANSFER
19235 WALNUT DR., CITY OF INDUSTRY, CA

4. Generator's Phone (714 529-5956

5. Transporter 1 Company Name

OMEGA RECOVERY SERVICES

7. Transporter 2 Company Name

9. Designated Facility Name and Site Address

OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA 90602

10. US EPA ID Number

ICIAID0142121450101

A. State Manifest Document Number

88614635

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone (213) 698-0991

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

CANADY 45001

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

a. WASTE PERCHLOROETHYLENE ORM-A UN 339# 1897

12. Containers
No. Type010
01112 DIM CLOS G13. Total
Quantity14. Unit
Wt/Vol

Waste No.

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a. 01

b.

c.

d.

15. Special Handling Instructions and Additional Information

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

JAMES WHELAN

Signature

James L. Whelan

Month Day Year

10/10/89

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

ROBERT T. CIRINGIONI

Signature

Robert T. Ciringioni

Month Day Year

10/10/89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

FRANK FORD

Signature

Frank Ford

Month Day Year

10/20/89

Do Not Write Below This Line

While: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA CALL 1-800-852-7660

GENERATOR

TRANSPORTER

FACILITY

EPA 6022-A (1/86)

EPA 8700-22

Rev. 9-86) Previous editions are obsolete.

Please print or type. (Form designed for use on elite (12-pitch typewriter).

88681783
IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-900-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD 982 502 932		Manifest Document No. 1 1 1		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address NEWTON HEAT TREATING INC. 19235 EAST WALNUT DR., CITY OF INDUSTRY, CA 91744						A. State Manifest Document Number 38681783			
4. Generator's Phone (714) 529-5956						B. State Generator's ID			
5. Transporter 1 Company Name OMEGA RECOVERY SERVICES						6. US EPA ID Number CAD 042 245 001		C. State Transporter's ID 110237	
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone 213 698-0991	
9. Designated Facility Name and Site Address OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602						10. US EPA ID Number CAD 042 245 001		E. State Transporter's ID	
								F. Transporter's Phone	
								G. State Facility's ID CAD 042 245 001	
								H. Facility's Phone 213 698-0991	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers No. Type		13. Total Quantity	
a. HAZARDOUS WASTE LIQUID, N.O.S ORM-A NA 9189 (PERCHLOROETHYLENE 60%, WATER 40%)						004 dm		002206	
b.								State 211,133	
c.								EPA/Other E-002, D039	
d.								State	
								EPA/Other	
J. Additional Descriptions for Materials Listed Above PROFIEL NUMBER B 10828						K. Handling Codes for Wastes Listed Above a. 01 b. c. d.			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name PAUL BRODERICK					Signature <i>Paul Broderick</i>			Month Day Year 12/20/91	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name Robert J. CIRINGOM					Signature <i>Robert J. Ciringom</i>			Month Day Year 12/20/91	
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name					Signature			Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name John HAUTE					Signature <i>John Haute</i>			Month Day Year 12/20/91	